


Mack GU813 Mounting Location




Left Side Frame Rail



Mounted Unit

Clearance at this point
needs to be about $\frac{1}{4}$ ".



After Completion

